



INDICATIVE
UNIT WEIGHT
700 g



See on our
website

Must be used for tack welding only and remove before completing welding. Avoid exposing the magnets to heat sources of over 80°C for too long.

- Adjust-O Magnetic square to easily hold metal workpieces at 45 or 90°
- Made with powerful magnets, it possesses an On/Off switch very practical for setting up
- Easy to clean after turning off the device
- MXE13 struts can be added

- Max. Pull force: □ 40kg
- Dimensions: 111x95x29mm